

Fluke 772 and 773 Milliamp Process Clamp Meters

Technical Data

Get more time.



Use the Fluke 772 and 773 to:

- Measure 4 to 20 mA signals without “breaking the loop” just like the innovative and popular Fluke 771 Process Milliamp Clampmeter
- Source 4 to 20 mA signals for testing control system I/O or I/Ps
- Simulate 4 to 20 mA signals for testing control system I/O
- Measure 4 to 20 mA signals with in-circuit measurement
- Simultaneously measure mA in-circuit with 24 V loop power for powering and testing transmitters
- Source mA output signals in a linear ramp or 25 % step output
 - Automatically change the 4 to 20 mA output for remote testing
- Power saving features, auto-off, backlight timeout extend battery life

Fluke 773 features:

- DC voltage measurement to verify 24 V power supplies or voltage I/O signals
- Source dc voltage to test input devices that accept a 1 to 5 volt or 0 to 10 volt signal
- Scaled mA output provides a continuous mA signal that corresponds to the 4 to 20 mA signal measured by the mA clamp
 - Output mA signal enables a logging DMM or other device to record the 4 to 20 mA signal without breaking the loop
- mA in/out: simultaneously measure the mA signal with the clamp and source a mA signal
 - Apply a mA input signal to a device and measure its 4 to 20 mA output on devices such as valves or mA isolators
- Voltage output linear ramp or 25 % step output
 - Automatically change the voltage output for remote testing

Functions

| | mA measure w/jaw | mA measure In circuit | mA source | mA sim | Loop power 24 V | DCV source 0-10 V | DCV measure 0-30 V | Scaled mA output to mA input | mA in/out |
|-----|------------------|-----------------------|-----------|--------|-----------------|-------------------|--------------------|------------------------------|-----------|
| 771 | • | | | | | | | | |
| 772 | • | • | • | • | • | | | | |
| 773 | • | • | • | • | • | • | • | • | • |

Functional specifications

| | Function | Resolution and range | Accuracy | Notes |
|---------------|-----------------|----------------------|------------------|---|
| 771, 772, 773 | mA measurement | 0 to 20.99 mA | 0.2 % + 2 counts | Measured by clamp |
| | | 21.0 mA to 100.0 mA | 1 % + 5 counts | |
| 772 and 773 | mA measurement | 0 to 24.00 mA | 0.2 % + 2 counts | Measured in series with test jacks |
| 772 and 773 | mA source | 0 to 24.00 mA | 0.2 % + 2 counts | Maximum mA drive: 24 mA into 1,000 ohms |
| 772 and 773 | mA simulate | 0 to 24.00 mA | 0.2 % + 2 counts | Maximum voltage 50 V dc |
| 773 | Voltage source | 0 to 10.00 V dc | 0.2 % + 2 counts | 2 mA maximum drive current |
| 773 | Voltage measure | 0 to 30.00 V dc | 0.2 % + 2 counts | |

General specifications 772 and 773

| | |
|-----------------------------------|--|
| Influence of earth's field | < 0.12 mA |
| Battery | (4) 1.5 V, Alkaline, IEC LR6 |
| Working hours | 12 hours @ 12 mA source into 500 ohms |
| Size (HxWxL) | 772, 773: 41.3 mm x 76 mm x 248 mm 771: 59 mm x 38 mm x 212 mm |
| Weight | 772, 773: 415 g 771: 260 g |
| Operating temperature | -10 °C to 50 °C |
| Storage temperature | -25 °C to 60 °C |
| Operating humidity | < 90 % @ < 30 °C; < 75 % @ 30 ~ 55 °C |
| Operating altitude | 0 ~ 2,000 m |
| Storage altitude | None |
| IP rating | IP 40 |
| Vibration requirements | Random 2 g, 5 Hz to 500 Hz |
| Drop test | Passes 1 meter drop test (except the jaw) |
| EMI, RFI, EMC | Meets applicable requirements in EN61326-1 Note: For current measurement w/jaw, add 1 mA to specification for EMC field strengths of 1 V/m up to 3 V/m |
| Temperature coefficients | 0.1/°C x specified accuracy for temperature < 18 °C or > 28 °C) |
| Warranty | Three-years, one-year on mA clamp assembly and cable |



Fluke. Keeping your world up and running.®

Ordering information

Fluke-772 Milliamp Process Clamp Meter
Fluke-773 Milliamp Process Clamp Meter

Included accessories

Soft carrying case, test leads, alligator clips, hanging strap and user's manual.



772



773

Fluke Corporation
 PO Box 9090, Everett, WA 98206 U.S.A.

Fluke Europe B.V.
 PO Box 1186, 5602 BD
 Eindhoven, The Netherlands

For more information call:
 In the U.S.A. (800) 443-5853 or
 Fax (425) 446-5116
 In Europe/M-East/Africa +31 (0) 40 2675 200 or
 Fax +31 (0) 40 2675 222
 In Canada (800)-36-FLUKE or
 Fax (905) 890-6866
 From other countries +1 (425) 446-5500 or
 Fax +1 (425) 446-5116
 Web access: <http://www.fluke.com>

©2009 Fluke Corporation. Specifications subject to change without notice.
 Pub_ID 11541-eng, rev 01

Modification of this document is not permitted without written permission from Fluke Corporation.